

Oil Field Environmental Incident Summary

Incident: 20140717102612 **Date/Time of Notice:** 07/17/2014 10:26

Responsible Party: Secure energy services

Well Operator: SECURE ENERGY SERVICES USA, LLC

Well Name: Secure energy services Sorenson SWD #!

Field Name: UNION CENTER

Well File #: 90250

Date Incident: 7/15/2014 **Time Incident:** 13:15

Facility ID Number:

County: MCKENZIE

Twp: 149

Rng: 98

Sec: 6

Qtr: SW SW

Location Description: Spill was contained within tank farm.

Submitted By: Sean Hammersmark

Received By:

Contact Person: Sean Hammersmark
13964 West Front St
Williston, ND 58801

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Tank Overflow

Release Contained in Dike: Yes - On Constructed Well Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	2	Barrels	2	Barrels		
Brine	40	Barrels	40	Barrels		

Other

Description of Other Released Contaminant:

Spill was salt water with a little bit of oil.

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

Minimal

Areal Extent:

Spill was Contained in Tank Farm

Potential Environmental Impacts:

None

Action Taken or Planned:

We are no longer going to have new operators in the control room until proper training has been provided.

Wastes Disposal Location: The spill was contained in tank farm and automatic sumps started up immediately returning all collected waste back into the system.

Agencies Involved:

Updates

Date: 7/17/2014 **Status:** Reviewed - Assigned to Other Agency

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a tank overflow, remained on location within the diking according to the report. NDIC retains oversight.